



*Quality and Value
Through Engineering*


◆ Signet Filament Replacement Kit

The 1004 Kit is for fabs who do not use the 37-1413 Processed Screws (OEM p/n F1413001). The processed screws are not required when either the 47-1401 silver or 32-5393 moly filament connector rods are used.

VSEA - IMPLANTER PARTS
A2F, CF4/5, 350D/DE, CF/DF3000

Signet Filament Replacement Kit

This Signet Filament Replacement Kit offers both value and convenience. All parts required for filament replacement are packaged together which saves time purchasing, stocking and installing.



Signet Products Kit Part Number 1004

The parts included in the kit are:

Signet Part #	OEM Part #	Qty	Description
37-7136	7136001	1	Filament
37-8883	8883001	2	Filament Insulator
37-9192	9192001	2	Hitch Pin Clip

Ref. = Design Alteration of OEM Part

Signet Products Inc.

2 Davis Drive
Belmont, CA 94002

PDS1004 Revised 01/21/04

Phone 650 592-3575

Fax 650 592-7223

e-mail sales@signetproducts.com

Web www.signetproducts.com